

### IMPORTANT NOTICE

Part Number - LKC102020

If the manifold is replacing manifold that has failed by warping; care must be taken to ensure that damage has not been sustained to the manifold studs in the cylinder head.

Failure to do so could result in premature failure of the new manifold due to it not being held at a uniform clamping load.

After fitment of the manifold the bolts should be checked again after 50-100 miles and if necessary re-torqued.

#### Disclaimer

These fitting instructions are intended for general guidance only. No responsibility will be accepted for damage to persons, property, equipment or vehicles caused during or arising from the fitment or using of this product. Fitting this item to your vehicle may constitute a vehicle modification and therefore we strongly recommend that you check the product complies with local laws and legislation and always inform the vehicle's insurance company accordingly.

