

Important Information

BRITPART

The quality parts for Land Rovers

Part Number - LR009732

Please be aware that on this part investigation using diagnostic equipment points to there being a fuel pressure sensor issue, which when renewed can rectify the problem. However, the root cause of this issue is likely to be corroded connections in the fuel pressure sensor harness connector and renewing the sensor alone may not permanently repair the problem. When fitting the new regulator please check the mating plug on the vehicles wiring loom for corrosion.

Land Rover recommend the fitting of repair harness YMQ503320.

Britpart, The Grove, Craven Arms, Shropshire, SY7 8DA United Kingdom www.britpart.com

Disclaimer

These fitting instructions are intended for general guidance only. No responsibility will be accepted for damage to persons, property, equipment or vehicles caused during or arising from the fitment or using of this product. Fitting this item to your vehicle may constitute a vehicle modification and therefore we strongly recommend that you check the product complies with local laws and legislation and always inform the vehicle's insurance company accordingly.

Vr: 1.

