

Fitting Kit Instructions for STC1180

All the bolts in this fitting kit must be tightened to 28/35 Nm except for the pillar loop fixing bolts on a 5 door Discovery and 4 door Range Rover fitted with a height adjuster in the front. The bolts for these applications must be tightened to 25/32 Nm.

The fitting configuration must comply with the vehicle manufacturers instructions.