

The quality parts for Land Rovers

Important Information

Please read prior to fitting TVK000180

Please take care to correctly remove the red breather plug from the unit prior to fitment. There have been instances where customers have not removed this plug correctly and have left plastic inside which has subsequently blocked the breather.

To remove the plug you must push down on the bottom collar while pulling the plug, please do not force the plug out as this may cause it to break and leave pieces of plastic inside the breather.

Britpart, The Grove, Craven Arms, Shropshire, SY7 8DA United Kingdom Tel: +44 (0) 1588 672711 Fax: +44 (0) 1588 672660 Email: sales@britpart.co.uk www.britpart.co.uk